

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.emsl.com>cinnaslab@EMSL.com

EMSL Order: 041226130

CustomerID: ECOL44

CustomerPO: 10ZZ

ProjectID: BOA

Attn: **Mark Woodke**
Ecology & Environment, Inc.
720 3rd Ave
Suite 1700
Seattle, WA 98104

Phone: (206) 624-9537
Fax: (206) 621-9832
Received: 10/04/12 2:20 PM
Analysis Date: 10/17/2012
Collected: 9/26/2012

Project: **BURLINGTON HILL/ 1022****Test Report: PLM Analysis of Bulk Samples for Asbestos via EPA 600/R-93/116 Method with CARB 435 Prep (Milling) Level A for 0.25% Target Analytical Sensitivity**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
12090102 041226130-0001	LOCATION 1- WEST	Tan Non-Fibrous Homogeneous		99.50% Non-fibrous (other)	0.50% Actinolite
12090104 041226130-0002	LOCATION 1- MIDDLE	Tan Non-Fibrous Homogeneous		99.25% Non-fibrous (other)	0.75% Actinolite
12090105 041226130-0003	LOCATION 1- EAST	Gray Non-Fibrous Homogeneous		99.50% Non-fibrous (other)	0.50% Actinolite
12090107 041226130-0004	LOCATION 2- ALONG DRIVE-WAY	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
12090109 041226130-0005	LOCATION 2- WEST OF GARAGE	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
12090111 041226130-0006	LOCATION 3- NORTH END QUARRY	Gray Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
12090112 041226130-0007	LOCATION 3- SOUTH END QUARRY	Gray Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Garret Vliet (9)

Stephen Siegel, CIH, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to the cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The test results contained within this report meet the requirements of NELAC unless otherwise specified. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ

Initial report from 10/17/2012 10:00:14

Test Report PLMPTC-7.25.0 Printed: 10/17/2012 10:00:14 AM

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.emsl.com>cinnaslab@EMSL.com

EMSL Order: 041226130

CustomerID: ECOL44

CustomerPO: 10ZZ

ProjectID: BOA

Attn: **Mark Woodke**
Ecology & Environment, Inc.
720 3rd Ave
Suite 1700
Seattle, WA 98104

Phone: (206) 624-9537
Fax: (206) 621-9832
Received: 10/04/12 2:20 PM
Analysis Date: 10/17/2012
Collected: 9/26/2012

Project: **BURLINGTON HILL/ 1022****Test Report: PLM Analysis of Bulk Samples for Asbestos via EPA 600/R-93/116 Method
with CARB 435 Prep (Milling) Level A for 0.25% Target Analytical Sensitivity**

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
12090114 041226130-0008	LOCATION 4- NORTH END	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
12090115 041226130-0009	LOCATION 4- SOUTH END	Tan Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Garret Vliet (9)

Stephen Siegel, CIH, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to the cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The test results contained within this report meet the requirements of NELAC unless otherwise specified. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ

Initial report from 10/17/2012 10:00:14